

# VEHICLE INSPECTION REPORT

**YN18UGY**

## Daf CF 340

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 08/05/2018

Year 2018

Mileage 219,568 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRASM4100G197158

Body Style Skiploader

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

### HIAB MULTILIFT EQUIPMENT

### Tyres

| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |


## Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Door nsf  
Scratched  
Over 25mm Thru Paint



2: Qtr Panel Trim ns  
Broken  
Replace





3: Door osf  
Chipped  
Multiple Chips



4: Carpets Front  
Holed  
Over 3mm



5: Seat Base Cover osf  
Holed  
Over 3mm

**Interior**

|                         |      |                             |    |
|-------------------------|------|-----------------------------|----|
| <b>Carpet Condition</b> | Poor | <b>Upholstery Condition</b> | OK |
| <b>Seat Condition</b>   | Poor | <b>Odour</b>                | -  |
| Engine Runs             | OK   | No Excessive Smoking        | OK |
| EML light illuminated   | OK   | DPF light illuminated       | OK |
| ABS light illuminated   | OK   |                             |    |